

## **Distribution Design Catalogue**

**Unmetered Supply** 

Section 16

© Copyright of Western Power - ABN 18540492861


CU	Date	REVISION	DESCRIPTION OF REVISION
	Sept 2002		Original Issue
	May 2003		See Amendment List
	April 2006		See Amendment List
	Sept 2007		See Amendment List
	May 2009		See Amendment List
	June 2009		See Amendment List
	Sep 2009		See Amendment List
	Dec 2009		Revised Format
	Feb 2016		See Amendment List
	May 2016		See Amendment List
	June 2016		See Amendment List
	Nov 2017		See Amendment List
	Dec 2018		See Amendment List
	Sep 2019		See Amendment List
	Feb 2021		See Amendment List
	May 2022		See Amendment List
	Sep 2022		See Amendment List

## **UM Drawings Revision List**

	SINGLE PHASE SUPPLIED UMS PIT UMO	1	DIRECT CONNECTION UM03	THREE PHASE SUPPLIED UMS PIT UM04
DRAWN: JRR DATE: 22-04-2014 DRG. No.				

## **Unmetered Supply CU List**

CU	CUDESCRIPTION
UM1	Single phase supplied ums pit
UM3_NR	Direct connection - fit fuse only
UM3_R	Direct connection - install red spot and fit fuse
UM3_FS	Direct connection to below ground service pit - install flood seal below great to service pit
UM_4	T-Off with 25 mm <sup>2</sup> from LV feeder cable




## CU CU Description

UM1		Single phase supplied ums pit			
Item Number	Stock Code	DESCRIPTION	Qty Rod	Unit of Measure	Remarks
1	FB0055	Single phase pit	1	ea	
2	FE0110	fuse holder kit	1	ea	
3	GF2102	fuse, 20 Amp	1	ea	
4	CZ0307	instruction tag	1	ea	

westernpower \_

Uncontrolled document when printed. Printed copy expires one week from print date.

DM # 23850326




|--|

UM3_NR		Direct Connection to pillar - fit fuse only (no red s	spot req	uired)	
Item Number	Stock Code	DESCRIPTION	Qty Rod	Unit of Measure	Remarks
1	CZ0307	instruction tag	1	ea	
2	GF0917	red spot fuse, 20 Amp	1	ea	
4	FE0112	Termination kit	1	ea	If WP Cable

UM3_R		Direct Connection to pillar - install red spot and f	it fuse		
Item Number	Stock Code	DESCRIPTION	Qty Rod	Unit of Measure	Remarks
1	CZ0307	instruction tag	1	ea	
2	GF0917	red spot fuse, 20 Amp	1	ea	
3	GF0121	red spot fuse holder	1	ea	
4	FE0112	Termination kit	1	ea	If WP Cable

UM3_FS	Direc	t Connection to below ground service pit - install fl	ood sea	al and fit fu	se
Item Number	Stock Code	DESCRIPTION	Qty Rod	Unit of Measure	Remarks
1	CZ0307	instruction tag	1	ea	
2	FE0110	Fuse holder kit	1	ea	
3	GF2102	Fuse 20 amp	1	ea	
4	FE0112	Termination kit	1	ea	If WP Cable
5	EE1432	16mm <sup>2</sup> cable	2	m	



CU		CU Description			
UM_4		T-Off with 25mm2 from LV Feeder Cable $**$			
Item Number	Stock Code	DESCRIPTION	Qty Rod	Unit of Measure	Remarks
1	FB0051	Three phase pit	1	ea	
2	FE0110	fuse holder kit	1	ea	
3	GF2102	fuse, 20 Amp	1	ea	
4	FE0109	4-finger glove and black heatshrink sleeving	1	ea	
5	FE0102	red heatshrink sleeving	1	ea	
6	FE0103	white heatshrink sleeving	1	ea	
7	FE0104	blue heatshrink sleeving	1	ea	
8	FE0071	black heatshrink sleeving	1	ea	
9	CC0852	4-port connector	4	ea	
11	EE1432	16mm conductor	3	m	
12	CZ0307	instruction tag	1	ea	
13	CE0055	earth clamp	1	ea	
14	CE0135	earth rod	1	ea	

\*\* Use UM3\_FS if more than one required.