

SAMPLE: Equipment schedule for unmetered supply connection / disconnection / relocation

Equipment to be connected/disconnected/relocated

Type of equipment	Customer reference no. (if known)	No of units	Exact wattage of unit *	Total wattage	Daily hours of operation	Manufacturer's model number & description of installed equipment	Western Power asset? YES / NO
<i>Lamps</i>	<i>MRWA LM910</i>	<i>56</i>	<i>10.70W</i>	<i>599W</i>	<i>24</i>	<i>Aldridge Ind.</i>	<i>NO</i>
<i>Transformer</i>	<i>MRWA LM910</i>	<i>56</i>	<i>2.14W</i>	<i>120W</i>	<i>24</i>	<i>Aldridge Ind.</i>	<i>NO</i>
<i>Controller</i>	<i>MRWA LM910</i>	<i>1</i>	<i>100W</i>	<i>100W</i>	<i>24</i>	<i>Aldridge Ind.</i>	<i>NO</i>
	TOTAL	<i>113</i>	TOTAL #	<i>819W</i>		Attached Scaled Map must show location of equipment listed. * Wattage of control equipment to be included.	